- Site Service Report -

IRD SO#: 11167 IRD Ref:

From: Richard Maynard To:

Project Name: Delhi LTPP

Project Location: Delhi, CA Hwy 99 NB

Service Date(s): 7-14-11

Weather: Sunny & Warm

Job Description: Routine site maintenance

Work Completed: Tested all sensors and power settings.

Cleaned cabinet and electronics.

Verified proper operation of all system components.

Work Remaining: None

Parts Used: None

Mileage / Travel Time: N/A

Time Spent on Site: N/A

Notes: Concrete starting to break away from sides of homerun conduit for frame 2 in

the right wheel path.

Action Items:

| Item | Action Required | Ownership |
|------|-----------------------------------|-----------|
| 1. | Monitor homerun conduit for pad 2 | |